


LAMPIRAN

Lampiran 1.1 Cucukan Macam Kain M 22866



Lampiran 1.2 *Chek Sheet* Pergantian Sub Valve

CHEK SHEET

NO. MESIN :

TGL	MASALAH	PERBAIKAN	NAMA
22/11	Dress out 2 kopas roll Agelokor	Ganti surface roll & prog roll 2 per	P. H.
22/11	Sub Kustari	Ganti Ho U/Cu	h.a
2/3	tsu jaring	- posisi No. 2	7052
2/4	Snarl Che pin	Ganti valve band main	7052
23/4	Tsunhori	Ganti sub valve	7052

Lampiran 1.3 Penandaan Pada Rol Hasil Perbaikan

